

Update for OCT/ 22

Landfill

- Wood pile will be burnt when final dutch elm are brought in
- bins changed as required

Water plant & Distribution system-lots of fouling issues with uf filter, cleaned and lowered flow

- New membranes on site, awaiting cleaning chemicals to practice on uf
- Cleaned both uf and ro with new chemicals, worked well on organics?
- ro taken offline because of high pressure, tried cleaning to no avail, contacted dillion for advice, tried to inject hydrogen peroxide but i am having chemical pump issues,parts ordered, will resume ro operation as soon as possible
- 2" park line- request to locate shutoff by nelsons shop, will begin the hunt in the spring
- Alpha automation onsite, changed two pressure transducers and emg pump switch
- Asked Derek schultz about communications from pump house ,will be supplying options and pricing
- Checking on internet security/water plant dial in program-Delco
- Need clarification on uf integrity testing, daily or on runtime
- RO brought back online nov 3 running great ,suspect lake turnover and we are logging more things on raw water such as temp and conductivity to give us some data to predict what the lake is doing , next hurdle will be manganese so we will be testing for manganese every two days on the raw water , coagulant will have to be used for these events when we predict them, this will reduce coagulant costs and filter trouble
- hydrants drained once more and ready for winter
- Curb stops- exercised 9 and had to replace 5

Equipment and Tools -routine equipment maintenance and repairs on going

- Service equipment as required, all in cold storage
- Hall floor cleaner repaired and back in service

Town buildings-no issues –monitoring as required

- Changed all town building furnace filters, Library furnace was repaired –gas valve failure
- light bulbs changed in office and library and shades cleaned

Education- will be scheduling first aid course this month

Lagoon/sewer-,antizyme being added, logging and testing on going

- Top shot on site oct 31 and completed the 4 manhole bottom repairs, mainline cracking was observed on two mains, awaiting report and will discuss options going forward
- Sewer relining-will need a site visit plus camera to determine repair and cost

Grass / Tree

- removed and cleaned up trees from various storms, trimming boulevard trees

Streets – Ongoing maintenance